

KW53ZPZ Full History breakdown since new

Mileage	Date	Full Service	Item
3014	20/11/2004		Pre New Car Check
5034	02/02/2005		Crankcase Ven Mod - Dealer Recall
6017	19/02/2005		Service - 18k + Compartment Filter
8023	01/03/2005		Dealer - replace door seals n/s/r & n/s/f
18025	17/06/2006		Full Service - Wipers/Sparks/Cabin
33945	12/01/2007		Stratsone - Winter Check
21890	13/01/2007		MOT HiQ Ilkeston - Fail on Seatbelt replaced under warrenty
23045	15/05/2007		Wheel Alignment HiQ Ilkeston
28011	28/07/2007		Full Service - Wipers/ Mintex Extreme front pads /Sparks/Cabin
29969	22/12/2007		Winter Check
29969	22/12/2007		Winter Check Stratstone - Notts
33013	13/07/2008		Full Service / Wiper blades
35434	08/11/2008		Winter Check (Notts Saab)
37600	10/01/2009		MOT HiQ Ilkeston
40801	28/02/2009		Replaced pulley belt and Brake Fluid change - Notts Saab
41010	20/04/2009		Full Service
41289	25/04/2009		Abbott ECU Upgrade (Notts Saab)
43202	09/01/2010		Winter Check (Notts Saab)
44416	23/01/2010		MOT - front headlight beam adjusted
51862	06/01/2011		MOT - brake pads low inner front
51862	06/01/2011		Replace rear shocks, Winter Check, Adjust Handbrake Cable, replace HB spring, Replace gearbox seal and top up geararbox oil
54376	05/05/2011		New Windscreen Autoglass
55230	16/06/2011		Service In Oil & filter + Spark plugs - one misfire - cured on replacement - no error code thrown
56825	28/08/2011		Tyre Check: FNS 7mm / FPS 6.54mm / RNS 7.5mm / RPS 7.5mm + Front Pads Low / Rear Medium
58028	30/09/2011		Front Saab Discs / Pads set Notts Saab
60300	26/11/2011		Replace Wiper Blades
61132	20/01/2012		MOT - Passed (Notts Saab) + Oil Change GM Synth, Oil Filter GM Gen + Spark Plugs Change NGK - BCP6ES-11
63000	20/06/2012		DI Cassette Changed - Gen - Neo Brothers
69500			Clean JR Oil Filter + Change Cabin Filter (Man) + Oil & Filter Change GM Genuine
69518	31/08/2012		Summer Check & Adjust Handbrake shoes, pulley belt removed and all pulleys checked, repair to split vac hose on throttle body, - Notts Saab
70001	24/12/2012		Tyres Costco - x 4 Michelin Prem 3 HP (£378)
72085	03/01/2013		Nottingham Saab, MOT, Rear pads, discs, shoes, Winter Check (£471.44)
76k	28/07/2013		Change wipers, oil +filter, sparks, air filter, modify front grill
			Notts Saab, New Clutch, New slave cylinder, new pipe from clutrch to gear linkage
82k	24/07/2014		Clean JR Oil Filter + Oil & Filter Change GM Genuine
85545	06/01/2015		Notts Saab, winter check, brake fluid check, aux belt check + MOT

88k			Front pads / Clean JR Oil Filter + Oil & Filter Change GM Genuine / Sparks
89474	13/08/2015		New DI Cassette, replace handbrake both read cables, general check, ISF anti roll bar link replaced
96000			Two Tyres
103000	01/06/2017		New Suspension Bilstein Shocks and Springs / New Engine Coolant / Belt Checked and fine
104k	01/08/2017		Sparks, oil, filter, new sump plug, grease doors
104k	07/08/2017		Fit new Saab, discs and pads to front, vibration on heavy braking was issue, only part worn pads, disks shot!
			Blue vacuum pipes replaced in engine bay
			New fuel filter (rusted) and fuel pump (fuel gauge slow)
			New CV Join on Driver side / New Connecting plate for subframe
			Subframe bushes
			Rose joints lower & trailing arm with polyflex
			Oil cooler (o rings as well)
110k	Jul-18		Yearly service, oil change, filter, spark plugs
			New Battery - High Spec Crank Exide
			Rear bumper respray for slight scuff
			Bonnet partial respray for small scratches
			Handbrake cables on both sides replaced and adjusted
			Headlamp Polish
	10/06/2020		Engine Breather pipe that goes to one way valve on top!
	25/06/2020		Air Conditioning Blend Door Fix - Longer Shaft installed both Sides
115k	25/06/2020		Cabin filter, oil change, service
			Driveside hub replaced and ABS ring driveshaft all in one
			Broken pipe in front of engine bay - vacuum style hose - replaced
121k	30/04/2022		Sparks, oil, filter, new sump plug, cabin filter, clean air filter
125k	06/08/2022		Change Thermostatic Switch/ Thermostat/ Top Rad Hose / Flush with Dex-Cool Premix - preventative work / New Drivers side Wiper Blade / New Boost Vacuum Controller (due to crack from removal of hoses)
126k	12/08/2022		Early MOT due to scrape in carpark/ Front Bumper repair and respray driver side
	Mar-23		Rollbar Front Link Drop Arms Meyle - replaced x 2 / Headlamp Polish
			Bonnet Struts Meyle - replaced x 2
125,024	10/06/2023		Replace 4 sparks, grease DI Regas Aircon (down to 100g -> topped to 850g), Radiator replaced and bottom hose due to tiny leak, coolant reused and topped up. Dex-Cool
125,200	24/06/2023		Cabin Filter Change, slightly damp NB: sticky tape up on the foam.
	24/05/2023		Oil filter change, Oil Dexos2, Sump washer changed